Phillips/ConocoPhillips Incidents Timeline

Nov 1, 2001
"WHITE POWDER/ENVELOPE MAY HAVE POWDER AT REFINERY

LT. BROWN WATCH COMMENDER WILL DO THREAT ASSESSMENT & IF NECESSARY BRING THE BAGGED PACKAGE HERE TO THE OFFICE TO BE TAKEN TO LAB FOR ANALYSIS

May 31, 2002
UPSETS BEGAN AT 5 A.M./STABLIZED @ 6 A.M./SAMPLES TAKEN

Jul 10, 2002
90 min. shelter-in-place order due to black smoke emanating from refinery - partial plant shut down

LOST STEAM TURBINES/PLANT UNDERGOING CONTROLLED SHTDWN/

PLUME GOING OFF SITE/LVL UPGRADED TO A 3/LARGE BLACK CLOUD/CAN ACTIVATED IN ZONES 1 & 2 (CROCKETT) SEE 72 HR REPORT

Dec 2, 2002
GASOLINE VAPOR RELEASE FRM PRESSURE RELEASE VALVE WHILE

LOADING GASOLINE AT DOCKS/DURATION OF RELEASE WAS 3 MINS OF VAPOR RELEASE/NO ACTION TAKEN

Jan 24, 2003
INTO THE BAY/THAT CAUSED MEDIA ALERT FOR OPTION TO BREAK INTO PROGRAMMING/FLURRY OF MEDIA CALLED HANDLED BY A # OF HAZMAT STAFF/INCIDENT DOWNGRADED TO LVL 1

CWS LVL 2 PUSH BUTTON ACTIVATION FOR A HYDROCARBON RELEASE

Feb 7, 2003
PHILLIPS RESPONDED NOTICED FAINT ODOR NO READINGS

STRONG ODOR FROM PHILLIPS REFINERY, CALLED SHELTER IN PLACE

Jul 15, 2003
PLUGGED LEAK 100 GALS SPILLED, AND SPILLED MATERIAL LEFT IN SOIL

AMTRAK TRAIN STRUCK TRUCK CARRYING SODIUM HYPOCHLORITE

Jul 23, 2004
FLARING- WILL PROBABLY CONTIN FOR ANOTHER WEEK

Oct 12, 2004
3-4 layers od old gasoline on top of water on the UST. Public Works was going to hire a contractor to remove the rank and contaminated soil

LOCATED ABANDONED UST UNDER PARKER AVE STRNG DIESEL ODORS

Oct 20, 2004
HYDROGEN FIRE LEVEL 1 INCIDENT

Jan 4, 2005
FACILITY WILL BE SHUTING DOWN HYDROGEN PLANT

Oct 31, 2004
Plant 19, F-1 flare gas knockout drum line 14 inch flange was opened while process gases were flowing, instead of another flare line flange that emptied and suppose to be opened. Release of process gases and plant emergency called.

FLANGE LEAK ON SOUR LINE

May 1, 2006
Hour long shelter-in-place order due to release of hazardous material.

LEVEL 3-POWER FAILURE RESULTED IN EMERG SHUTDOWN & FLARING

Feb 20, 2005
FLARE ACTIVITY-NO OFFSITE CONSEQUENCES

Feb 15, 2007
MINOR SOUR HYDROCARBON STREAM LEAKING FROM STRIPPER

Mar 18, 2007
Sulphur plant shutdown due to electrical failure. XS sulfur to flare

FLARE DUE TO SULPHUR UNIT DOWN, EXCEEDED REPORTABLE QUANTITY

May 18, 2007
Sulphur plant shutdown due to electrical failure. XS sulfur to flare.

May 28, 2008
Refinery malfunction

Nov 22, 2008
DOUBLE HOPPER TRAILER, ONE LOST 1/2 LOAD OF PETROLEUM COKE

Jan 4, 2009
Unit shutdown

Mar 19, 2009
Crockett odor complaints

Apr 21, 2009
Unit shut down, said to be due to "planned maintenance."

Sep 29, 2009
Flaring

Nov 2001 | Dec 2001 | May 2002 | Jun 2002 | Jul 2002 | Aug 2002 | Sep 2002 | Oct 2002 | Nov 2002 | Dec 2002 | Jan 2003 | Feb 2003 | Mar 2003 | Apr 2003 | May 2003 | Jun 2003 | Jul 2003 | Jul 2004 | Aug 2004 | Sep 2004 | Oct 2004 | Nov 2004 | Dec 2004 | Jan 2005 | Feb 2005 | May 2006 | Jun 2006 | Feb 2007 | Mar 2007 | Apr 2007 | May 2007 | May 2008 | Jun 2008 | Nov 2008 | Dec 2008 | Jan 2009 | Feb 2009 | Mar 2009 | Apr 2009 | May 2009 | Jun 2009 | Jul 2009 | Aug 2009 | Sep 2009